

OFFICE OF THE EXECUTIVE ENGINEER

P.W. [SOUTH] DIVISION PUNE – 1

OUTWARD NO.DB/2929/2019

OFFICE OF THE EXECUTIVE ENGINEER

P.W.[SOUTH] DIVISION PUNE

DATE- 20.04.2019.

BUILDING SAFETY CERTIFICATE

Subject :- Requirement of Building Safety Certificate.

Reference :- 1) Your Letter Dated on 08/04/2019.

2) Assistant Engineer Gr-1, P.W.Sub-Division, No. 2 Haveli, Letter No.
370/2019 Dt. 20/04/2019

The site **The Walnut School, at survey no. 3/2 Village Shivane, Tal. Haveli, Dist. Pune** has been inspected by our concerned P.W. Subdivision No.2 Haveli and as per their report mentioned in reference no. 2 the building is formed to be safe. So far as the structural design is concerned, **M/s Sunil Patil & Associates, Pune** is responsible for the same as per structural Stability certificate given by him on dated 09.10.2017.

For Walnut School
Mo dal..
Manager



For Walnut School
D.Khane
Principal

[Signature]
[D.N.Deshpande]
Executive Engineer
P.W.(South) Division Pune.1

✓ **Copy-** The Walnut School, at survey no. 3/2 Village Shivane, Tal. Haveli Dist. Pune.

Copy- Assistant Engineer Gr-1, P.W.Sub-Division, No. 2 Haveli for information